



Fig 3: The root system was damage, record on Jan 23.



Fig 4: The root system was damage, record on Jan 23.



Fig 5: The root system was damage, record on Jan 23.



Fig 6: The truck and trench, record on Jan 23.



Fig 7: The truck and trench, record on Jan 23.



Fig 8: The truck and trench, record on Jan 23.



Fig 9. Heavy duty machine on surface, record on Jan 23.



Fig 10. Bobcat and concrete near trunk, record on Jan 23.

<p>Fig 11. Trench backfill soil, record on Jan 24.</p>	<p>Fig 12. Trench backfill soil, record on Jan 24.</p>
<p>Fig 13. The surface ground cover was badly mangled, record on Jan 24.</p>	

VIII. SIGNATURE

YM WU	Qualified Arborist	SIGN		DATE	26 Jan 2010
TC LAM	Associate	SIGN		DATE	26 Jan 2010
ERIC LEE	Consultant	SIGN		DATE	26 Jan 2010